Tino	A. Ka be He (Please	Print\					_	Page	of	
/ ∕/atc	hman	- mit)					W O Numb	er		11
	ted From Hunt	Valley		То	(utha	rville	W.O Humb	oi		
	13		-9		<u>C</u>	7 911/2	-	8		
	Exception Chair	Marker No.	w.o.	Track	Rail	Switch	Coc	des	Status	Repair
tem	From	То	Number*	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.				•						
2.		3967	<b>医</b>							
3.										
4.			。 第一次就是							
5.										
6.										
7.										- 3
8.			diegijalis, s						**	
9.			ing skipping is							<del></del>
m	COMMENTS		aptroaps are consti					L1		L
, T		NO NO	ing to	uspe ects	Notes	of Proc	to six	drea	ditio.	3
)_ ) <del>-</del>		NO NO	ng I	uspe ects	notes	of Ame	to Sic	diea	ditio	3
) )-	Wara Switch							diea		
)		n in the area	a of Inspecte	ed Ye	95		0			
	ere all single op	n in the area	a of Inspecte	ed Ye	95		0			
Wws_	ere all single op	n in the area	a of Inspecte	ed Ye	95		0			
	ere all single op	n in the area	a of Inspecte	ed Yenecting re	es_ od type sv	N	0			
98	ere all single op NO	in the area perating med	a of Inspecte thanism & con	ed Yenecting re	esod type sv	Nvitches inside	O_ area and op			
Re	ere all single op NONO SPECIAL IN ason for spec	in the area perating med ISPECTIO	a of Inspecte thanism & con	ed Yenecting re	esod type sv	Nvitches inside	Oarea and op	eratated in	each positi	
Re	ere all single op NO SPECIAL IN	in the area perating med ISPECTIO	a of Inspecte thanism & con	ed Yenecting re	esod type sv	Nvitches inside	O_ area and op	eratated in	each positi	

Name •//atcl	(Please	Print)			Date		W.O Numb	Page er 1839	of /	/ *
ect	ted From ביי			то С	Spia Spi	SIN P	-			
	Exception Cha	in Marker No.	w.o.	Track	Rail	Switch	Cod	des	Status	Repair
Item	From	То	, Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1,										
2.										
3.										
4.										
-										
5. 6.			的第三人称单数 第二人称							
7.	-		ELLER		-+					jų .
8.										
9.		1	elson som Frank i skut e			····	<u></u>			
tem	COMMENTS									
5									39	9
We	Were Switc		of Inspecte		es × v/3			eratated in	ach noeiti	on 2
'es	NO <del>&lt;</del> _			•	31		and and op		saon positi	017 7
	SPECIAL II	NSPECTIO	N Yes	١	10 <u>%</u>	_				
Rea	ason for spec	cial Inspect	ion ?							
Trac	ck Inspector S	ianature					Supervisory	O 115	. 111	1

ime /atchi pecte	( Please Print)						rade	of l	
.ρect∈		œ	_		10/2015	W.O Numbe			
	ed From CAMDEN	_	To (	<u> </u>	LOH				
	Exception Chain Marker No.	W.O.	Track	Rail	Switch	Cod	es	Status	Repair
em	From To	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.:									
2.									
3.		Salast Cathor							
4.									
5.									
3.									
7.									
3.									
9.									
n	COMMENTS								
_	RIDING INSPEC NO NEW DEFECTS N	OTEN OR	OBSER	EVED IN	ARGA	Nitt			
-									
$\vdash$									
-									
=									
$\neg$									
-									
L					SIRVAL				
	Were Switch in the are				ONCY NO				_
	ere all single operating me	chanism & co	necting r	od type sv	witches inside a	area and op	eratated in	each posit	ion ?
s	NO_X_								
	ODEOLAL INODEST	ON		NO Å-					
	SPECIAL INSPECTI	ON Yes_		NO_X					
	ason for special Inspe	ction?							
Rea									
Rea									.1
								111	0
	ck Inspector Signature					Supervisor	y Cretifica	tion_U_	Stark
	ck Inspector Signature					Supervisor	y Cretifica	tion <u>Uf</u>	Styl

)	A. Rabet (Please					-10-15		Page	of	
^/atc	hman						W.O Numb	er 183	9096	/ *
,Jec	ted From Lo	165prin	29	To c	Land	en -Bu	# Pan	IN		
							Participan in the second	W.		
	Exception Chair	Marker No.	w.o.	Track	Rail	Switch	Cod	les	Status	Repair
Item	From	То	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.				*						
2.	3									
3.										
4.			in Duitellast							
	8		(*) (*) (*) (*)							
5.									4	
€.										
7.									- 6	
8.										
9.										
		No N	ding :	FRET	pection 1	on Du	e to s	now C	fond,+	100
<u></u>		No R	ding Te	Fre-	rection 1	on Du	e to s	NOW C	lond, t	100
<u></u>		No R	ding pe	Fre-t	perti	on Du	e to s	now C	fond, +	100
<u></u>			a of Inspecte		pection of the second	on Dy		now C	lond, t	100
y w	Were Switch	h in the are	a of Inspecte	ed Ye	95	N	0	W. W.		
	<i>Were Switcl</i> ere all single op	h in the are	a of Inspecte	ed Ye	95	N	0	W. W.		
	<i>Were Switcl</i> ere all single op	h in the are	a of Inspecte	ed Ye	95	N	0	W. W.		
	<i>Were Switcl</i> ere all single op	h in the are	a of Inspecte	ed Ye	es_ od type sv	Note the second of the second	0	W. W.		
es	Were Switch ere all single opNO	h in the are perating med	a of Inspecte chanism & co	ed Ye	esod type sw		O_ area and op	eratated in o		
es	Were Switch ere all single opNO SPECIAL IN	h in the are perating med	a of Inspecte chanism & co	ed Ye	esod type sw		O_ area and op	eratated in o		
es Rea	Were Switch ere all single opNO SPECIAL IN	h in the are perating med	a of Inspecte chanism & co	ed Ye	esod type sw	//itches inside	O_ area and op	eratated in o	each position	

me	J 501			Date 3	111/2015		Page	of (		
1	( Please	Print)					144 - 5 -	100	1-05-	. 4
	hman	16		т.	1		W.O Numb	er_183	6753	
nspec	ted From HUN	T VALLEY	-	То	LUTHE	RVILLE	•			
	Exception Chai	in Marker No.	W.O.	Track	Rail	Switch	Cod	les	Status	Repair
Item	From	То	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.			L CONTROL OF	0.5						
2.	- 92									
3.			PERMIT							
4.										
5.										
6.										
7,:									724	
8.										
9.										
em	COMMENTS									
	RIDING IN	CONTOROL								
	No New D	PEFECTS NOT	ED IN ARE	A						
_/										
		·								
	Mona Civita	Ja in Alaa awa		l V	- V	ONLY N				
۱۸/		th in the area			25	ONUE NO	0	( ) 11		•
۷۷	ere all single o	perating med	nanism a co	necting re	od type sv	vitches inside	area and op	eratated in	eacn positi	on ?
3S	NOX	-								
	CDECIAL II	NEDECTIC	M Voc	,	VIO. 1:					
	SPECIAL II	NSPECTIC	in res_		νO_1					
Da	acon for one	معالمة	ion O							
Rea	ason for spec	ciai inspect	ion (							
									ú	/
_									011	
Tra	ck Inspector S	ignature					Supervisor	y Cretificat	ion//	Soll
1	Sal. O				2				1	1
	mou	-							3.	6

	( Please hmanted From ∠/∧ 1	,		то <	romwe	211 - BW	W.O Numb	er <u>/83</u>	3795.	<i>3</i> "
em	Exception Chair	To	W.O.	Track	Rail	Switch	Coc		Status	Repair
1.	From 5 425	10	Number	No.	E/W E W	No.	Comp.	Defect	S/Y/R	Y/N
	5 723	-			E &		R301	329	<u> </u>	
							+	327	Y	
_			A LUIS CONTRACTOR				<b> </b>			<b>-</b>
-				-						
-							<b>!</b>			
							-			
<u>.</u>			er Rain							
4			100 100 100				ļ		0.1	
4										
			Sudry E.							
	200' Line Ly of	North + Surt	+ Sou-	th c roug	of to	Hollins Idio	ferry ("outof	Bridge	GC NA	reds
)-		North + Surt	+ Sour	the cong	of to	Hollins	ferry "ovtot	Bridge	S.C. NA	redz
)	200' Live:							1 Bridge	Se N.	reds
)-		h in the area	of Inspecte	ed Ye	es	^	10		2	
w	Z 00' Liwe Liwe Vere Switcher all single op	<i>h in the area</i> perating mec	of Inspecte	ed Ye	es	^	10		2	
w	Were Switch ere all single op	h in the area perating med	of Inspecte hanism & co	ed Yenecting re	es_ od type sw	vitches inside	IOarea and op	eratated in	2	

itcl	( Please hman	,					W.O Numb	er		1
rspect	ted From Lot	herVille	~	То	Cold	pring	4	<b>%</b>		
	Exception Chair	Marker No.	W.O.	Track	Rail	Switch	Cod		Status	Repair
Item	From	То	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.	.81	X • Z	To be the second							
3.										
4.										
5.	- · ·			-						
6.										
7.						<del></del>				- 27
8.									**	
9.			Carl III							
em )	COMMENTS	Λ	Vo Ne	w ps	efect	le Non	led in	Are	a	
)	COMMENTS	Λ	Vo Ne	W Bs	rfect	teg Non	ledin	Are	- 1	
)	COMMENTS	Λ	Vo Ne	W Bs	rfect	ty Non	ledin	Are		
em								Are	***	
3-	Were Switch	n in the area	of Inspects	ed Ye	95_ ~	N	0			on ?
3		n in the area	of Inspects	ed Ye	95_ ~	N	0			on ?
3	Were Switch ere all single op	in the area	of Inspecte	ed Ye	esod type sv		0			on ?
3	Were Switcl ere all single op	in the area	of Inspecte	ed Ye	esod type sv		0			on ?
Wes	Were Switch ere all single opNO	in the area perating mech	of Inspecteranism & co	ed Ye	od type sw	Novitches inside	Oarea and op	eratated in	each positi	on ?
es	Were Switch ere all single op	in the area perating mech	of Inspecteranism & co	ed Ye	od type sw	Novitches inside	Oarea and op	eratated in	each positi	on ?
Wes	Were Switch ere all single opNO	in the area perating mech	of Inspecteranism & co	ed Ye	od type sw	Notition in the state of the st	Oarea and op	eratated in	each positi	on?
Wees_	Were Switch ere all single opNO	in the area perating mech ISPECTIO ial Inspecti	of Inspecteranism & co	ed Ye	od type sw	Notition in the state of the st	Oarea and op	eratated in	each positi	on?
Wees_	Were Switch ere all single opNO SPECIAL IN ason for spec	in the area perating mech ISPECTIO ial Inspecti	of Inspecteranism & co	ed Ye	od type sw	Notition in the state of the st	Oarea and op	eratated in	each positi	on?

·lame	( Please I	SLER Print)			Date	3/12/15	-	Page	1 of 2	
	hman				_		W.O Numl	per_ 1836	927	11
nspec	ted From CAM	DEN		То	Cow S	brin 6	<b>-</b>	2		
	Exception Chain	Marker No.	W.O.	Track	Rail	Switch	Co	des	Status	Repair
Item	From	То	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1,,	MT BOYAL STA.			· 1	W	-	R305	344	Y	
2.	KT KOYAL STA			- 1	w		R 305	311	Y	
3.										
4.										
	(8)									
5										
6.							Î			
7.										
8.					8					
9.			HIT DEL							
m	COMMENTS									
1	JUST SOUTH	OF MT1	ROYAL ST	A., TRA	<u>ck#1,</u>	U-69 U	VER BLOC	KS BEIN	G RUBE	SED ON
	Top (2),	U-69 RE	STRAINFA	& RAIL	SIDE	WORN, TI	RAINS JUST	STARTIN	GTO HIT	HARA
	GOING ARO	UND CUA	NE							
_										
$\perp$										
-										
_										
	Were Switch	in the area	of Inspecte	ed Y	es_X C	VAL	VO			
W	ere all single op				od type sy	witches inside		peratated in	each nociti	on 2
	NOX	oraling moor		noomig i	ou type of	mones made	o area aria of	ocialaleu in	cacii positi	OII :
_										
	SPECIAL IN	SPECTIO	N Yes		NO &					
	OI LONIE III	01 20110	1 103_		10_7					
R۵	ason for speci	al Inenacti	on 2							
. 16	ason for speci	ai iiispeci	OII :							
									, A	
~	ala la ancie de Ci								AK	and
	ck Inspector Sig						Supervisor	ry Cretificat	tion(VI)	witc
-,	- Solici				v.				1	1

Name	T Sc	HISLER		=	Date	3/12/15		Page	2 of 2	
	( Please hman ted From }	Print)	Œ	То			W.O Numb	er <u> / 83 (</u>		/ ".
	Exception Chai	n Marker No.	w.o.	Track	Rail	Switch	Cod	des	Status	Repair
Item	From	То	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1,				8						
2.			E Const.							
3.										
4.										
5.										
6.			un den vare							
7.										
8.										
9.										
m	COMMENTS									l
	R	DING IN	SPECTIO	12						
<u>}</u>										
	W 0					VISUAL				
W s	ere all single on		a <b>of Inspect</b> e hanism & col	necting r	es	switches inside	area and op	eratated in	each positi	on ?
	SPECIAL IN									
Rea	ason for spec	ial Inspect	tion ?							-
Tra	ck Inspector Si	gnature					Supervisor	y Cretifica	tion_M_{	royk
	T Sol	-0				Y)			~ <u>%</u>	

ате	( Please F	HISLET	ζ		Date	3/13/15		Page	of 2	
	hman Some	SELL	-	To L	<u>-INTHI</u>	CUH	W.O Numb	er <u>/83</u>	6966	/ *
	Exception Chain	Marker No.	W.O.	Track	Rail	Switch	Cod	tes	Status	Repair
ltem	From	То	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1,,									0	
2.		1060								
3.										
4.										
	27 96									
5.						1			10	l
6.								i		
7.										
8.										
9.			Acethur III							
m	COMMENTS									
) 									8	
								14		
W/s	Were Switch ere all single opeNOX SPECIAL IN	erating mec	hanism & coi	necting ro			nrea and op	eratated in	each positi	on?
Rea	ason for speci	al Inspect	ion ?							1
Trac	ck Inspector Sig			4		5	Supervisor	y Cretifica	tion <u>M</u>	2041
1	Jal.	,				8			(/	/

ame		CHISLER			Date	3/13/15		Page	2 of 2	
	( Please hman <u>5</u> ted From LuT	SELL		То	Bwi		W.O Number	er <u>/83</u>	6966	<u>/                                    </u>
	Exception Chain	Marker No.	W.O.	Track	Rail	Switch	Cod	les	Status	Repair
tem	From	То	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.				·					0	
2.	E	1.00								
3.										
4.										
							-			
5.							<b> </b>			
3.									-	
7.										
							<b>-</b>	-	:4	
). ).										
<u>.                                    </u>	COMMENTS	I			ll					
) <del>-</del>										
								8		
s	Were Switch ere all single op NO × SPECIAL IN ason for speci	erating mech	nanism & co	necting r	od type sv	vitches inside	area and op			on ?
	ck Inspector Sig			16			Supervisor		116	Sout

lame,	A-Rabett		2		Date 3	-15-1	5	Page	of	
itcl nspec	( Please hman ted From	ŕ	후 6.	То	Lint	hicom	W.O Numbe	er <u> 1846</u>	503Z	<u>/ "                                   </u>
	Exception Chair	n Marker No.	W.O.	Track	Rail	Switch	Cod	es	Status	Repair
ltem	From	То	Number	No.	E/W	No.	Comp.	Defect	S/Y/R	Y/N
1.										
2.				-						
3.										
4.										
_										
5.									34	
6.										
7. 8.							-			
9.										
m	COMMENTS									
) <u> </u>									*	
$\frac{1}{w}$	<i>Were Switcl</i> ere all single op	h in the area	-			No		eratated in	each positi	on ?
es							·		·	
Rea	ason for spec	ial Inspecti	ion ?					S		
Tra	ck Inspector Si	gnature		;#			Supervisor	y Cretifica	tion M. K	ant